

HP-PB Token Ring Release Notes

HP 9000 Networking



**Manufacturing Part Number: J2166-90048
E1200**

United States

© Copyright 2000 Hewlett-Packard Company.

Legal Notices

The information in this document is subject to change without notice.

Hewlett-Packard makes no warranty of any kind with regard to this manual, including, but not limited to, the implied warranties of merchantability and fitness for a particular purpose. Hewlett-Packard shall not be held liable for errors contained herein or direct, indirect, special, incidental or consequential damages in connection with the furnishing, performance, or use of this material.

Warranty. A copy of the specific warranty terms applicable to your Hewlett-Packard product and replacement parts can be obtained from your local Sales and Service Office.

Year 2000 Compliance Warranty. Manufacturer warrants that all HP Products will be "Year 2000 Compliant." Year 2000 Compliant products will perform without error, loss of data, or loss of functionality on account of any inability to process, calculate, compare or sequence date data accurately. In addition, Year 2000 Compliant products will not cause any associated HP products or any systems in which they may be used to fail in any of the ways described above. This Year 2000 Compliance warranty will remain in effect through December 31, 2000, notwithstanding any other warranty period specified in this Agreement.

Restricted Rights Legend. Use, duplication or disclosure by the U.S. Government is subject to restrictions as set forth in subparagraph (c) (1) (ii) of the Rights in Technical Data and Computer Software clause at DFARS 252.227-7013 for DOD agencies, and subparagraphs (c) (1) and (c) (2) of the Commercial Computer Software Restricted Rights clause at FAR 52.227-19 for other agencies.

HEWLETT-PACKARD COMPANY
3000 Hanover Street
Palo Alto, California 94304
U.S.A.

Use of this manual and flexible disk(s) or tape cartridge(s) supplied for this pack is restricted to this product only. Additional copies of the programs may be made for security and back-up purposes only. Resale of the programs in their present form or with alterations, is expressly prohibited.

Copyright Notices. ©copyright 1983-2000 Hewlett-Packard Company, all rights reserved.

Reproduction, adaptation, or translation of this document without prior written permission is prohibited, except as allowed under the copyright laws.

©copyright 1979, 1980, 1983, 1985-93 Regents of the University of California

This software is based in part on the Fourth Berkeley Software Distribution under license

from the Regents of the University of California.

©copyright 1980, 1984, 1986 Novell, Inc.

©copyright 1986-1992 Sun Microsystems, Inc.

©copyright 1985-86, 1988 Massachusetts Institute of Technology. ©copyright 1989-93 The Open Software Foundation, Inc.

©copyright 1986 Digital Equipment Corporation.

©copyright 1990 Motorola, Inc.

©copyright 1990, 1991, 1992 Cornell University

©copyright 1989-1991 The University of Maryland

©copyright 1988 Carnegie Mellon University

Trademark Notices UNIX is a registered trademark of The Open Group.

X Window System is a trademark of the Massachusetts Institute of Technology.

MS-DOS and Microsoft are U.S. registered trademarks of Microsoft Corporation.

OSF/Motif is a trademark of the Open Software Foundation, Inc. in the U.S. and other countries.

HP-PB Token Ring Release Notes for HP-UX 11i

What's in This Version

The following information is for HP-PB Token Ring adapters for the V-Class servers and the B, C, and J-Class workstations.

Known Problems and Workarounds

The HP-PB Token Ring driver does not implement the functionality to change the SNMP MIB ifAdmin status.

Compatibility Information and Installation Requirements

Software Requirements

- HP-UX 11i operating system

Hardware Requirements

- HP-UX SPP2200 V-Class server or B, C, or J-Class workstation
- CD-ROM drive

Memory and Disk Space Requirements

- 16 MB memory
- 550 KB free disk space

Install/Upgrade With System UP or Down

- Install the HP-PB Token Ring adapter with the system down.
- One reboot is required for installation and configuration.

Installing and Upgrading HP-PB Token Ring

The HP-PB Token Ring card is not customer-installable on the SPP2200 V-Class server, but it is customer-configurable. We recommend that only qualified HP Customer Engineers access the SPP2200 system to install I/O cards.

The HP-PB Token Ring card is customer-installable and configurable on the B, C, and J-Class workstations.

Patches and Fixes for this Version

Patch PHNE_20536:

- **I/O slowdown due to HP-PB Token Ring driver absorbing a large number of IOVRs.**

The HP-PB Token Ring driver does not combine small requests into a large one, so when it gets a fragmented I/O request with too many small fragments from the higher layer, it will try to map each of the fragments separately. This will consume a large number of IOVRs.

The driver code has been modified to combine small fragments into a large request so it does not consume too many IOVRs.

- **The HP-PB Token Ring driver may show too many outbound errors/ discards.**

One of the internal driver data structure has insufficient number of entries, causing the driver to drop outbound packets. There were also large numbers of outbound errors and discards using HP-PB Token Ring running at 16MB. The fix is to increase the number of entries in this data structure.

- **NIO Token Ring fails to rebind IP after cable reconnect.**

The driver sends LINKUP and then goes through a reset cycle, which can take as much as 35 seconds on cable reconnect. Since the application finds that the link is up, it sends bind requests, however, they fail as the driver is still in reset state. The fix is to send LINKUP only after reset completion.

Patch PHNE_18922:

- **The system panics with a Data page fault when HP-PB Token Ring is present in the system.**

The HP-PB Token Ring driver does not validate the memory range of a data structure before writing to it. This leads to memory corruption and the system may panic. The fix is to perform the range check before accessing the data structure, therefore preventing memory corruption and subsequent panic.

Patch PHNE_17355:

- **The card can go into a hang state and an error message will be logged in the `/var/adm/syslog/syslog.log` file.**

A bug in the firmware can create a situation such that the firmware sends the inbound frames with the size larger than the configured MTU. However, the driver does not provide enough buffers for DMA. The DMA hardware then gives an error which causes the card and driver to go to a fatal error (hung) state. The driver will now drop those packets that arrive with the larger size, thus preventing the hung state. Indication of the dropped packets is logged in the NetTL log file.

- **CISCO HSRP addresses cannot be reached.**

The HP-PB Token Ring driver treats all of the functional addresses as multicast addresses. This causes a concern if any system uses functional addresses as the primary source address. The driver now checks for IP multicast functional addresses and converts only those to general multicast functional addresses. Other functional addresses are used without any transformation.

- **The system may panic when it is heavily loaded and memory is low.**

The HP-PB Token Ring driver reuses a buffer chain even after it has been freed. Due to this, the card initially will appear to hang (no outbound is performed) and when the user tries to reset the hung interface card with the `lanadmin` command, the system will panic due to a wrong memory access. More robust checks have been implemented and proper cleanup is done whenever memory is freed.

- **System panics with Data page fault in the HP-PB Token Ring driver.**

The HP-PB Token Ring driver writes to a wrong memory address which may lead to a system panic. The driver now validates the address range before using the memory address.

- **The HP-PB Token Ring driver shows the wrong value for “Operational Status” MIB object.**

The HP-PB Token Ring driver does not set the “Operational Status” MIB object to “UP” after the successful initialization of the driver/interface card. This leaves the value of this object always to “DOWN” even if the card is functional. The driver now marks the “Operational Status” as “UP” when driver initialization is successfully completed.

- **When the HP-PB Token Ring card is used with a Token Ring card supporting 4500 MTU size, the network may hang.**

Since the maximum size for the HP-PB Token Ring card is 4170, it will ignore incoming packets of a size greater than 4170. Some vendor cards support 4500 as the maximum MTU, therefore, the maximum MTU size for the HP-PB Token Ring card must be

increased. The maximum MTU size for the HP-PB Token Ring card has been increased to the standard 4500, and the default MTU is set to 4170. The user may increase this to 4500, using the `lanadmin` command.

- **SAM gives an error when configuring HP-PB Token Ring card.**

The cause of this defect was incorrect syntax usage for a shell command in the initialization script `/usr/sbin/hptoken_init`. The syntax has been corrected.

Patch PHNE_15000:

- **The IP multicast feature does not work.**

In the `token2_hw_req()` file, the code to swap the MAC address before setting the destination address to the functional address is not needed, since the driver gets the bits in the right format from the upper layer.